## This Page Is Inserted by IFW Operations and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

## IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.

Docket No.: 0545.033 Serial Number: 10/616,030

## REMARKS

In response to the Notice of Allowability dated March 30, 2004, FIGS. 1 and 4 have been amended. Entry of these amendments, reconsideration of the application, and allowance of the claims is respectfully requested. No new matter has been added.

Applicant awaits the issuance of a Notice of Allowance and Issue Fee Due.

If a telephone conference would be of assistance in advancing prosecution of the subject application, Applicant's undersigned attorney invites the Examiner to telephone him at the number provided.

Respectfully submitted,

Victor A. Cardona, Esq. Attorney for Applicant

Registration No. 44,589

Dated: June 25, 2004

HESLIN ROTHENBERG FARLEY & MESITI P.C.

5 Columbia Circle

Albany, New York 12203

Telephone: (518) 452-5600 Facsimile: (518) 452-5579

Customer No.: 23405

Title: Bearing Assembly Spacer Adjustment System and Method for Adjusting a Spacer

1/6




FIG. 1

PRIOR ART

MARKED UP COPY

Title: Bearing Assembly Spacer Adjustment System and Method for Adjusting a Spacer

4/6




FIG. 4